



Jefferson County West Virginia

Public Information

**TABLE 3
INTERNAL INSPECTION I&I RELATED DEFECTS SUMMARY**

MANHOLE NO.	COMMENT(S)	I&I FLOW (GPD)
	SUBSYSTEM 'CHT-R' - NO I&I RELATED DEFECTS OBSERVED	
	SUBSYSTEM 'CHT-S'	
S1A-S1	LEAKING JOINT 25' FROM MH S1A	2,000
S1A-S1	LEAKING JOINT 37' FROM MH S1A	7,500
	SUBSYSTEM 'RAN-Y' - NO I&I RELATED DEFECTS OBSERVED	
	SUBSYSTEM 'PSD-AA' - NO I&I RELATED DEFECTS OBSERVED	
	SUBSYSTEM 'PSD-JF' - NO I&I RELATED DEFECTS OBSERVED	
	SUBSYSTEM 'PSD-HH'	
HH29-HH28	BREAK-IN SERVICE LEAKING 44' FROM MH HH29	700
HH29-HH28	JOINT LEAK @ BREAK-IN SERVICE 97' FROM MH HH29	1,400
HH29-HH28	BREAK-IN SERVICE LEAKING 151' FROM MH HH29	400
HH29-HH28	BREAK-IN SERVICE LEAKING 154' FROM MH HH29	700
HH31-HH32	JOINT LEAK @ BREAK-IN SERVICE 72' FROM MH HH31	200
HH31-HH32	CRACKED PIPE 81' FROM MH HH31	200
HH31-HH32	BROKEN PIPE 88' FROM MH HH31	200
HH31-HH32	BROKEN LATERAL (PROTUSION DEPOSITTS) 126' FROM MH HH31	200
HH32-HH33	OPEN JOINT 118' FROM MH HH32	300
HH32-HH33	BROKEN PIPE 123' FROM MH HH32	3,000
HH33-HH35	OPEN JOINT 26' FROM MH HH33	700
HH36-HH37	SERVICE LATERAL LEAKING 41' FROM MH HH36	700
HH42-HH41	SERVICE LATERAL LEAKING 52' FROM PSD HH42	3,000
HH41-HH40	SERVICE LATERAL LEAKING 32' FROM PSD HH41	3,000
HH43-HH42	SERVICE LATERAL LEAKING 69' FROM PSD HH43	1,500
HH43-HH26	SERVICE LATERAL LEAKING 19' FROM PSD HH43	1,500
HH43-HH26	SERVICE LATERAL LEAKING 210' FROM PSD HH43	400
HH23-HH22	SERVICE LATERAL LEAKING 80' FROM MH HH23	1,500
HH22-HH21	SERVICE LATERAL LEAKING & ROOTS 45' FROM MH HH22	700
HH7-HH6	SERVICE LATERAL LEAKING 34' FROM MH HH7	100

TOTAL